



Number: GZHT90380071

Date: Aug 13, 2013

Applicant:

Sample Description:

Two (2) pieces of submitted sample said to be A9201 Injection lace up safety boots in Black.

Standard	:	EN ISO 20345: 2011
Size	:	UK 8, 9
Ref. No.	:	FS410(A8320)
Insert Plate	:	Steel plate
Toe Cap	:	DINKIE 459
Sole	:	Black dual density PU
Upper	:	Black buffalo leather
Vamp Lining	:	White fur lining
Quarter Lining	:	White fur lining
Tongue	:	-
Collar	:	-
Insole	:	White fur lining
Insock	:	Grey non-woven fabric board
Date Period Received/Date Test Started	:	Aug. 05, 2013

Test Result Please Refer To Attached Page(S).

Should you have any query on this report, you may contact at gzfootwear@intertek.com

Authorized By:
For Intertek Testing Services Shenzhen Ltd.
Guangzhou GDD Branch



Huang Ning, Andy
Assistant General Manager

AZ / tiffanydeng

FJ90380071

Page 1 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch
 3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
 Economic & Technological Development District, Guangzhou, China
 深圳天祥量技服有限公司广州区分公司
 中国广州天河区大道235号恒大厦3楼
 Tel: (8620)2232 1668 / 8396 6868 Fax: (8620)8222 7490 Postcode:510730



Number: GZHT90380071

Tests Conducted (As Requested By The Applicant)

Cold Insulation Of Sole Complex (Whole Footwear) (EN ISO 20344:2011(5.13))

		<u>Requirement</u>	<u>Pass/Fail</u>
<u>Size 8</u>	Left:	*	Pass
	5°C Temperature Decrease And Except For The In sock, The Insulation Is Incorporated In The Footwear That It Cannot Be Removed Without Damaging The Footwear.		

Remark:

* = Max. 10°C Temperature Decrease On The Upper Surface Of The Insole.

Except For The In sock, The Insulation Shall Be Incorporated In The Footwear In Such A Manner That It Cannot Be Removed Without Damaging The Footwear.

Expanded Uncertainty: 1.10°C , With k=2.12 At 95% Confidence Level.

This report is made solely on the basis of your instructions and/or information and materials supplied by you. It is not intended to be a recommendation for any particular course of action. Intertek does not accept a duty of care or any other responsibility to any person other than the Client in respect of this report and only accepts liability to the Client insofar as is expressly contained in the terms and conditions governing Intertek's provision of services to you. Intertek makes no warranties or representations either express or implied with respect to this report save as provided for in those terms and conditions. We have aimed to conduct the Review on a diligent and careful basis and we do not accept any liability to you for any loss arising out of or in connection with this report, in contract, tort, by statute or otherwise, except in the event of our gross negligence or wilful misconduct.



Number: GZHT90380071

Tests Conducted (As Requested By The Applicant)



AZ / tiffanydeng

Page 3 Of 3

Intertek Testing Services Shenzhen Ltd. Guangzhou GDD Branch
3/F., Hengyun Building, 235 Kaifa Ave., Guangzhou
Economic & Technological Development District, Guangzhou, China
深圳天祥质量技术服务有限公司广州开发区分公司
中国广州经济技术开发区开发大道 235 号恒运大厦 3 楼
Tel: (8620)2232 1668 / 8396 6868 Fax: (8620)8222 7490 Postcode:510730